



WORKMAN | NYDEGGER
INTELLECTUAL PROPERTY ATTORNEYS

COFC

1000 EAGLE GATE TOWER, 60 EAST SOUTH TEMPLE | SALT LAKE CITY, UTAH 84111
TEL: (801) 533-9800 | FAX: (801) 328-1707 | WWW.WNLAW.COM

PATENT
Docket No. 15436.222.1.1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE



In re application of

Donald A. Blackwell

Serial No.: 10/764,592

Filed: Jan. 23, 2004

For: HOUSING FOR HOT PLUGGABLE NETWORK TAPS

Examiner: Boris Chervinsky

Patent No.: 7,102,887 B2

Issue Date: Sept. 5, 2006

Art Unit
2835

REQUEST FOR A CERTIFICATE OF CORRECTION
UNDER 37 C.F.R. § 1.323

Attn: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
AUG 13 2008
of Correction

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

08/12/2008 HBLANCO 00000026 7102887

61 FC:1811

100.00 00
RECEIVED-USPTO
Patent Publication

AUG 13 2008

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23-3178. Duplicate copies of this letter are enclosed.

Dated this 6 day of August, 2008.

Respectfully submitted,



R. Burns Israelsen
Attorney for Patentee
Registration No. 42,685
Customer No. 022913

RBI:ngm
Docket No. 15436.222.1.1
Certificate of Correction Documents (with check)

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on this 6 day of August, 2008.



Transmitted: REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323,
PTO Form 1050 and Check No. 15928 for \$100.00

RECEIVED-USPTO
Publication

AUG 13 2008



WORKMAN | NYDEGGER
INTELLECTUAL PROPERTY ATTORNEYS

1000 EAGLE GATE TOWER, 60 EAST SOUTH TEMPLE | SALT LAKE CITY, UTAH 84111
TEL: (801) 533-9800 | FAX: (801) 328-1707 | WWW.WNLAW.COM

PATENT
Docket No. 15436.222.1.1

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE



Continuation-in-part re application of

Donald A. Blackwell

Serial No.: 10/764,592

Filed: Jan. 23, 2004

For: HOUSING FOR HOT PLUGGABLE NETWORK TAPS

Examiner: Boris Chervinsky

Patent No.: 7,102,887 B2

Issue Date: Sept. 5, 2006

Art Unit
2835

REQUEST FOR A CERTIFICATE OF CORRECTION
UNDER 37 C.F.R. § 1.323

Attn: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

In accordance with the provisions of 37 C.F.R. § 1.323 which implement 35 U.S.C. § 255, the Commissioner is respectfully requested to issue a Certificate of Correction to correct mistakes in the above-identified patent. The enclosed Patent Office Form 1050 reflects the desired corrections. Also enclosed please find a check in the amount of \$100.00 to cover the costs for issuance of this certificate.

RECEIVED-USPTO
Patent Collection

AUG 13 2008

The Commissioner is hereby authorized to charge payment of any fees associated with this communication or credit any overpayment to Deposit Account No. 23-3178. Duplicate copies of this letter are enclosed.

Dated this 6 day of August, 2008.

Respectfully submitted,




R. Burns Israelsen
Attorney for Patentee
Registration No. 42,685
Customer No. 022913

RBI:ngm
Docket No. 15436.222.1.1
Certificate of Correction Documents (with check)

CERTIFICATE OF DEPOSIT UNDER 37 C.F.R. § 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service as first class mail, postage prepaid, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on this 6 day of August, 2008.



Transmitted: REQUEST FOR A CERTIFICATE OF CORRECTION UNDER 37 C.F.R. § 1.323,
PTO Form 1050 and Check No. 15928 for \$100.00

RECEIVED-UCPTO
Patent Collection

AUG 13 2008

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,102,887 B2

Page 1 of 2

APPLICATION NO. : 10/764,592

ISSUE DATE : Sept. 5, 2006

INVENTOR(S) : Donald A. Blackwell

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 1, replace Fig. 1 with the figure depicted herein below, wherein the label for the chassis has been changed from "02" to --102--




Fig. 1

MAILING ADDRESS OF SENDER (Please do not use customer number)

R. Burns Israelsen, Esq., WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

RECEIVED-USPTO
Patent Publication

AUG 13 2008

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,102,887 B2

Page 2 of 2

APPLICATION NO. : 10/764,592

ISSUE DATE : Sept. 5, 2006

INVENTOR(S) : Donald A. Blackwell

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 20, after "modules", insert --.--

Column 6

Line 11, change "200" to --100--

Line 13, change "202" to --102--

Line 31, change "200" to --102--

Line 58, change "100" to --102--

Column 7

Line 10, change "202" to --102--

Line 15, change "200" to --100--

Line 34, change "100 or 200." to --100.--

Column 10

Line 28, remove [network taps]

Line 31, remove [network taps]

Line 38, remove [network taps]

MAILING ADDRESS OF SENDER (Please do not use customer number)

R. Burns Israelsen, Esq., WORKMAN NYDEGGER

1000 Eagle Gate Tower

60 East South Temple

Salt Lake City, Utah 84111

RECEIVED-USPTO
Application

AUG 13 2008

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,102,887 B2

Page 1 of 2

APPLICATION NO. : 10/764,592

ISSUE DATE : Sept. 5, 2006

INVENTOR(S) : Donald A. Blackwell

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Drawings

Sheet 1, replace Fig. 1 with the figure depicted herein below, wherein the label for the chassis has been changed from "02" to -102-




Fig. 1

MAILING ADDRESS OF SENDER (Please do not use customer number)

R. Burns Israelsen, Esq., WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

RECEIVED-USPTO
Publication

AUG 13 2008

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO. : 7,102,887 B2

Page 2 of 2

APPLICATION NO. : 10/764,592

ISSUE DATE : Sept. 5, 2006

INVENTOR(S) : Donald A. Blackwell

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1

Line 20, after "modules", insert --.--

Column 6

Line 11, change "200" to --100--

Line 13, change "202" to --102--

Line 31, change "200" to --102--

Line 58, change "100" to --102--

Column 7

Line 10, change "202" to --102--

Line 15, change "200" to --100--

Line 34, change "100 or 200." to --100.--

Column 10

Line 28, remove [network taps]

Line 31, remove [network taps]

Line 38, remove [network taps]

MAILING ADDRESS OF SENDER (Please do not use customer number)

R. Burns Israelsen, Esq., WORKMAN NYDEGGER
1000 Eagle Gate Tower
60 East South Temple
Salt Lake City, Utah 84111

RECEIVED-USPTO
Patent Publication

AUG 13 2008

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing the burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.